



Customer LLANGOLLEN MUSEUM
Contact Dave Crane ()


Resource Jackson Holland

Address Parade Street
Llangollen
LL20 8PW

Job type CCTV Survey - Pre booked

Reference CCTV5257

Date 15/05/2024 08:00



Dave Crane



1. Risk Assessment

	Answer	Notes
Has site been made safe before commencement of works with applicable barriers, signage, tape etc?	Yes	
Are there any other Engineers working with you today?	No	
Do you have the correct PPE to carry out the job safely?	Yes	
Is your equipment fit for purpose to complete the job safely?	Yes	

3. Service Sheet

	Answer	Notes
Are you able to gain safe access to the site?	Yes	
Any site/location details which will be helpful for future engineers?	Na	

Take an overview photo of work area before starting work



Full Description of works carried out (Before, During, After)

Arrived on site and carried out CCTV inspection of all accessible drainage file system was backed up so carried out high pressure water jetting to clear the blockage and holding waste then survey the drains finding fall between manhole one and two is poor. Customer is more interested in the surface drainage on site as they are changing the internal down pipes to external, was unable to pass two meters on both rwdp1 and 2, due to drinks bottles being stuck in the drains up two meters. However drains do go directly external away from the building allowing for new external downpipes to be connected to I was unable to locate main run and direction of the discharge line advised customer that when contractors come to change down pipes and exposed below ground drainage so we can carry out jetting and CCTV works to remove obstruction and locate discharge.

Payment Received?

No

Completion photo



20240515_115858



20240515_090808



20240515_115950



20240515_115858



20240515_120036



20240515_123527



20240515_094615



20240515_123520



20240515_094607



20240515_123518



20240515_092155



20240515_120121



20240515_090812



20240515_114503



20240515_114455



20240515_114449



20240515_114448



20240515_130654

